

Report on the
Napa - American Canyon Earthquake of 8.24.2014
Mw 6.0 - Performance of Lifelines

Bay Area Center for Regional Disaster
Resilience

Dublin, CA, February 20 2015

John Eiding
G&E Engineering Systems Inc.
eidinger@geEngineeringSystems.com

Agenda

- What Broke?
- What worked well?
- Why?
- DO Lifelines DO or NOT DO seismic mitigation?

August 24 2014. Shakemap, PGA (g), Max of NS, EW

Urban Areas (est. population as of June 2014, or latest data)

SHAKEMAP EARTHQUAKE
ID= 72282711
Magnitude = 6.00
Factored by 1.00
PGA-g

0.70 +	Red
0.55 - 0.70	Blue
0.40 - 0.55	Green
0.25 - 0.40	Magenta
0.20 - 0.25	Grey
0.15 - 0.20	Cyan
0.10 - 0.15	Yellow
0.05 - 0.10	Light Grey

INSTRUMENTS: % g

Sonoma County (491,829)

Napa County (139,045)

St Helena (5,814)

Santa Rosa (170,685)

Yountville (2,933)

Vacaville (94,275)

Rohnert Park (41,232)

Sonoma Valley (42,296)

Napa (76,915)

Petaluma (57,941)

Fairfield (109,320)

Vallejo (118,837)

Martinez (36,673)

San Rafael (57,713)

Richmond (106,516)


Berkeley (116,768)

San Francisco (825,863)

Oakland (400,740)

SERA 8.3.3.3

Place Names and Populations




September 15 2014. Shakemap, PGA (g), Max of NS, EW

SHAKEMAP EARTHQUAKE
ID= 72282711
Magnitude = 6.00
Factored by 1.00
PGA-g

0.70 +	Red
0.55 - 0.70	Blue
0.40 - 0.55	Green
0.25 - 0.40	Magenta
0.20 - 0.25	Grey
0.15 - 0.20	Cyan
0.10 - 0.15	Yellow
0.05 - 0.10	Light Grey

Scale. (Meters per Inch)
One Inch = 12444.
Meters/Pixel = 132.



This Area is Greatly Overstated! Due to Unsuitable Recordings in USGS ShakeMaps.

Two Giants Next to the Offending Ground Motion Instrument






Giant 1

Giant 2

Charlie Scawthorn

John Eidinger




	CE.68206	CE.68259
Latitude	38.0540	38.0548
Longitude	-122.2250	-122.2264
Distance to Epicenter (km)	20.0	19.9
PGA (NS) g	0.979 g	0.424 g
PGV (NS) cm/sec	22.2 cm/sec	19.8 cm/sec
SA (NS 0.3 sec, 5%) g	1.322 g	0.948 g
SA (NS 1.0 sec, 5%)	0.082 g	0.102 g
SA (NS 3.0 sec, 5%)	0.010 g	0.012 g
PGA (EW) g	0.517 g	0.177 g
PGV (EW) cm/sec	10.4 cm/sec	11.0 cm/sec
SA (EW 0.3 sec, 5%) g	0.432 g	0.323 g
SA (EW 1.0 sec, 5%)	0.115 g	0.122 g
SA (EW 3.0 sec, 5%)	0.010 g	< 0.01 g
PGA (V) g	0.316 g	0.172 g
PGV (V) cm/sec	7.42 cm/sec	6.33 cm/sec
SA (V 0.3 sec, 5%) g	0.518 g	0.360 g
SA (V 1.0 sec, 5%)	0.236 g	0.045 g
SA (V 3.0 sec, 5%)	0.003 g	0.004 g

Table 2-1. Instrument Recordings

Location of Water Pipe Breaks

NAPA ~ 125 Pipe Repairs
> 200 by Feb 2015



AMERICAN CANYON < 5 Pipe Repairs



VALLEJO ~ 54 Pipe Repairs



EBMUD ~ 2 Pipe Repairs a Day
is "business as usual"

SF ~ 2 Pipe Repairs

Age (years)	PVC	DI	CI	AC	RCCP	STL	Total	Pct of Total
< 20	6,600	225,600				100	232,300	13%
20-40	24,300	370,500	83,400	14,100		100	492,400	28%
40-60		12,300	466,700	167,200	9,900	59,800	715,900	40%
60-80			173,100			100,400	273,500	15%
80-100			55,100				55,100	3%
> 100			10,300				10,300	1%
Total	30,900	608,400	788,500	181,300	9,900	160,400	1,779,500	100%
	2%	34%	44%	10%	1%	9%	100%	


Table 4-1. Length of Water Pipe Mains – Napa (Feet)

Material	Repairs	% Repairs	% Pipe	Repair per Mile
AC	8	5%	10%	0.23
PVC	2	1%	2%	0.34
CI	123	75%	44%	0.82
DI	18	11%	34%	0.16
Steel	3	2%	9%	0.10
Other / unk	7	4%		
Total	163	100%		

Table 4-2. Repair Rates for Water Pipe



CAN SURFACE GEOLOGY EXPLAIN THE PIPE FAILURES?

- af Artificial fill
- Qhbm/af Estuarine deposits with areas of artificial fill
- Qhbm Estuarine deposits
- Qhay Latest Holocene alluvial deposits
- Qhay/Qhb Latest Holocene flood plain and basin deposits
- Qhs Holocene dune and beach sand
- Qhb Holocene basin deposits
- Qht Holocene terrace deposits
- Qhf Holocene fan deposits
- Qha Holocene alluvium, undifferentiated
- Qs Late Pleistocene to Holocene dune sands
- Qb Late Pleistocene to Holocene basin deposits
- Qt Late Pleistocene to Holocene terrace deposits
- Qf Late Pleistocene to Holocene fan deposits
- Qa Late Pleistocene to Holocene alluvium, undifferentiated
- Qpt Late Pleistocene terrace deposits
- Qpf Late Pleistocene fan deposits
- Qpa Late Pleistocene alluvium, undifferentiated
- Qpmt Late Pleistocene marine terrace deposits
- Qoa Early to middle Pleistocene alluvium
- Qomt Early to middle Pleistocene marine terrace deposits
- br Pre-Quaternary deposits and bedrock. Includes Quaternary landslides



CAN LIQUEFACTION EXPLAIN THE PIPE FAILURES?



Liquefaction
Susceptibility



CAN LIQUEFACTION EXPLAIN THE PIPE FAILURES?

- Pipes Already Repaired
- ▲ Pipes To Be Repaired

Liquefaction Susceptibility



CAN SURFACE FAULTING EXPLAIN THE PIPE FAILURES?



● Observed Locations of Surface Faulting



Quaternary Faults
(as of 2010)

Well Constrained



Moderately Constrained




Inferred Constrained



NAPA 2014. This map based on 160 known repairs as of September 2014.


Zones with Many Observations of Surface Faulting



- Pipes Already Repaired
- ▲ Pipes To Be Repaired

Previously Mapped Quaternary Faults (as of 2010)

- Well Constrained
- Moderately Constrained
- Inferred Constrained
- Mapped by others




Water Pipe Damage due to Shaking (excl. faulting or liquefaction)

- ALA 2001 models: $RR = 0.00187 * PGV$,
Adjust for pipe type; estimated soil corrosivity,
pipe diameter, pipe age.

<i>Pipe Type</i>	<i>ALA Model</i>	<i>Napa Actual</i>	<i>Comment</i>
<i>CI</i>	61.9	93	Very low R? Very Old? Pulse? Basin Effects? Shrink-swell? low c?
<i>PVC</i>	0.6	1	
<i>AC</i>	3.4	5	
<i>DI</i>	11.4	13	
<i>RCCP</i>	0.3	0	
<i>STL</i>	4.2	2	
<i>TOTAL</i>	81.8	114	

PG&E Customers without Power

1.4% of PG&E's 5,100,000 Customers



Yellow: Napa

Orange: Rohnert Park

Green: Saint Helena


Cyan: Santa Rosa

Red: Sonoma Valley

Grey: American Canyon

Blue: Vallejo

Number of Power Outages (number of faulted feeders, or part thereof)



Yellow: Napa
 Orange: Rohnert Park
 Green: Saint Helena
 Cyan: Santa Rosa

Red: Sonoma Valley
 Grey: American Canyon
 Blue: Vallejo

PG&E Power Outages

- High Voltage Transmission. Most had been seismic upgraded between 2000 and 2012, many \$millions. No material damage. No outages.
- Low Voltage Distribution. Pretty good performance. Why? Lessons learned in 1952 led PG&E to modify the way transformers are attached to wood poles: all through bolted, none on cross arms, none resting on platforms.

Distribution Outages

- 166 overhead, 3 underground
- 52 fuse related
- 41 wire related
- 10 equipment related
- 6 pole / cross arm / insulator related



Modern Control Building.... "many times stronger than code"

Old Control Building (Behind). Why replace it if it still plenty strong?
and Battery Enclosure (Front). Why build a Tesla when a Prius will do?



Everything OK at PGA = 0.30g.



Modern Transformer 230 kV - 60 kV (built 2010).

Anchorage capacity was sufficient so that $PGA = 0.30g$ was small enough to not overcome sliding / rocking.

Modern composite bushings.

Lots of cable slack.

No damage.



Modern Circuit Breaker 230 kV (built 2010).

Shake Table Tested to $PGA = 0.5g$.

Steel supports are elastic to $PGA \gg 1.0g$. (No "R" values allowed like for regular buildings)

Lots of cable slack.

No damage.



230 kV Horizontal Break switch atop heavily braced frame.

Lots of cable slack.

No damage.



Anshel Schiff, August 26, 2014

Prof Schiff is the “father” of seismic design of high voltage equipment.

Behind him is a modern circuit switcher (1999) (no damage) and a vintage power transformer (minor oil leaks)



115 kV - 12 kV Bank 1

Oil leaks appears to be from top pipe connections (as expected / common)



Modern Battery Racks.

No damage.





230 kV. Wave trap supported by two post-insulators, on same stand with Trench CCVT (composite)

Station Service Transformers. Heavy braced. No damage.



Vintage transformers. No damage at PGA $\sim 0.30g$. Well anchored.
A new parallel transformer bank was installed so these are somewhat "Redundant"



Replacing these surge arrestors would be a good thing; but there is redundancy. They did not fail in this earthquake.




115 kV CCVT Composite.



Upgrades of heavily loaded scaffolding might be a good thing.

Diagonal in scaffolding that was damaged in earthquake



12 kV Circuit Breaker and switches
some settlement



12 kV Circuit Breaker and switches
some settlement



115 kV SA (Composite) and
Pot Head (XLPE type)





Unanchored Cabinets rocked to these positions (formerly cabinets were tight against each other).





Gas Issues

- 160 loss of service due to damage to customer facilities
- PG&E responded to >8,000 service “tags” (report of gas odor, leak, safety check, ...)
- Total relights, appliance checks > 2,500 (926 in Napa, 110 in Vallejo)
- PG&E has replaced 200 feet of 26-inch diameter Steel pipe that underwent some fault offset. No damage in old pipe. New pipe is ~2 times tougher.
- PG&E is replacing 7,000 feet of 12-inch diameter PE pipe located in the fault zone (the pipe had no leak or apparent damage, but might be prone to pre-mature cracking)

64 m


Los-Cameros-Ave

Inferred location of buried power cables (not broken)

Utilities Building

1958 Building

Inferred location of buried water pipe (broken)







Line 021A.

**Surface
Cracking**



North

South



AT&T - Communications



Wall Panel Fell. Was held by 4 tabs, for future expansion. Building racking damaged the tabs. Panel fell onto HVAC equipment, damaging cooling system. PG&E power equipment was also damaged by the falling wall. Emergency generator failed to start. Back up batteries worked well. But, batteries need to be recharged.... a priority to get a generator to recharge the batteries. No real loss of service, as AT&T was able to respond.

Sewer

WWTP did well.
Why? founded on
clay (no
liquefaciton)

Sewer Pipes Broke
Repaired at fault
crossings

Residual pipe
damage remains to
be found



Zone with Concentrated Sewer Pipe Breaks




Figure 4-16. Location of Sewer Breaks


Type	Miles	Pct of Total
ABS Plastic	2	0.7%
AC	124	45.9
CI	1	0.4
Concrete	3	1.1
PVC	61	22.6
RCP	7	2.6
VCP	70	25.9
Other	2	0.7
Total	270	100%

Table 4-3. Length of Sewer Pipes – Napa (Miles)

Possible Rocking of Center Tower in Clarifier



Fire Following Earthquake



Fire Ignitions Attributed to the August 24 2014 Main Shock

No.	Time of Report (approx.)	Location	Description (see below)
1	0330	Orchard Ave	Napa Valley Mobile Home Park (NVMHP) – actually two ignitions – see narrative
2	0400	Laurel St. (no street number)	2 story, 2 unit residence, roof collapse, started fire
3	0500	162 Robin at Solano	Dbl wide home
4	0630	1990 Trower	Smoke inside structure
5	0730	770 Lincoln x Soscol	Electrical fire in substructure of a mobile home
6	1200	4072 Rohlffs Way x Fair	Kitchen fire in single story multi-unit senior housing complex

FFE

- There were several fire ignitions
- There was NO wind at the time of the earthquake
- If it had been windy (say 20 mph), with the loss of water pressure due to damage in the water system, then a LOT of Napa would have burned to the ground

Summary -Underground

- Damage to buried utility pipes is the ELEPHANT in the room.
- If we do not install seismic-resistant pipes in a proactive manner, some pipes are doomed in future earthquakes... Long outages.... Economic Consequences.... Loss of Water for Fire Fighting.... Raw sewage dumped into our waterways.... Gas leaks providing fuel for fires....
- ALA 2005 is a Guideline to design buried pipes. It might be time to make it a mandatory Standard.

Summary - Overhead

- Why did we do so well? IEEE 693 and Bellcore and lessons learned from past earthquakes. Thank you Anshel Schiff, Alex Tang (Nortel), Dennis Ostrom (SCE), Ed Matsuda (PG&E), Eric Fujisaki (PG&E), Leon Kempner (BPA), Lana Gilpin Jackson (BC Hydro), Ron Tognazini (LADWP), Craig Riker (SDG&E) and many others.
- These standards cost \$millions, and take decades to implement.

Do Utilities Do or Not Do?

- Do-ers: Knowledge of weaknesses, followed by careful assessment, followed by capital improvements.
- Non-Do-ers: Unaware of the risks. Or, aware of the risks, but unwillingness to fund.