

Anchorage M 7.1 Earthquake

Nov 30 2018, 8:29 am
(TCLEE 5B)

John Eidinger
G&E Engineering Systems Inc.
With contributions by:
John Dai, Southern California Edison
Bruce Maison, Structural Engineer
Engineers and staff of MEA, ML&P, CEA
October 15 2019

Copyright G&E Engineering Systems Inc. 2019.
May not be reproduced or distributed without obtaining prior permission.

Other TCLEE Reports

- Napa California 2014 (TCLEE 1 150 pp)
- Kyushu Japan 2016 (TCLEE 2 300 pp)
- Mexico City / Chiapas 2017 (TCLEE 3 100 pp)
- Hokkaido Japan 2018 (TCLEE 4 300 pp)
- Anchorage Alaska 2018 (TCLEE 5A 19 pp)
- Ridgecrest California 2019 (TCLEE 6)

Available at: www.geEngineeringSystems.com



Quick Overview

- 3 Electric Utilities (MEA, ML&P, CEA)
- ~ 375,000 people with PGA > 0.1 g
- >23 million Customer - Minutes of outages (might be higher)
- Many failures of 230 kV, 138 kV, 115 kV substation equipment and distribution feeders

Questions

- Question 1. “Weak Seismic Design is Okay” or “Brilliant Cost Effective Seismic Design” ?
- Question 2. Is the greater Anchorage electric system ready for the next $M \sim 9$ event (like 1964)?



Epicenter of M 7.1 Earthquake


ML&P. Serves Downtown Anchorage

MEA. Serves northern suburban / rural areas

CEA. Serves southern suburban / rural areas

Geographic Area of Interest in this M 7.1 Earthquake

Population in the box
~375,000 (2018)
~125,000 (1964)



Anchorage Municipal Light & Power (ML&P)
 Matanuska Electric Association (MEA)
 Chugach Electric Association (CEA)
 Seward Electrical System (SES)
 Golden Valley Electric Association (GVEA)

1964. Same utilities, but
 much smaller load and
 only the 115 kV grid existed

2018. New 138 kV and 230
 kV transmission,
 much larger load,
 several new gas-fired
 power plants


2018. Little to no evidence
 of seismic design at
 substations.

Weak bus design -
 widespread at nearly every
 substation.

No IEEE 693 Seismic tags
 that I could see
 on recently installed (post
 2005) 230 kV equipment

Note: Not all facilities shown

Area with Electric System
 Moderately Strong Shaking
 Resulting in Damage
 2018 M 7.1 Earthquake



Area with ~No Electric System,
High Shaking

14 feet right lateral offset at the 48" oil pipeline

2002 Denali M 7.9 Earthquake

(Denali_M7.9.pdf at www.geEngineeringSystems.com)


Area with Moderately Strong Shaking


Very Long Duration


Many Ground Failures

Many fatalities due to Tsunami

1964 M 9.0 Earthquake







Eagle River

Anchorage

Anchorage

Examples of damaged substations





7.06 km

Image Landsat / Copernicus

Google Earth

Imagery Date: 12/30/2016 lat 61.229575° lon -149.748460° elev 67m eye alt 30.39 km





MEA


- 16 of 22 substations immediately went black.
- 4 substations had damage to high voltage equipment (115 kV)
- New 10 x 17 MW power plant: 2 of 3 step up transformers (each 13.8 x 115 kV 75 MVA) tripped. Various other damage to plant building, fire sprinkler pipes, overhead crane, gas regulator station, etc. PGA -0.22g.
- Distribution damage.
- 42,600 of 65,000 meters (1 meter = 1 customer) were black at 11:30 am. 2,500 were black at 5 pm. 835 customers at 11:30 pm. About 15 Million CM.
- \$1.1 Million Repair Cost. Mitigation? none apparent.

MEA Briggs Substation




Rigid Bus. Surge Arrestors. Transformer slid, breaking 4 bushings.
PGA ~ 0.30g

MEA Pippel Substation



Candlestick Breaker. Surge Arrestors. Bus. 15 kV DS + CB. PGA ~ 0.30g



MEA Anderson Substation



Surge Arrestors. Circuit Switchers (candlestick breakers)
PGA ~ 0.30g

MEA Douglas Substation

Rigid Bus Expansion Joints, Bus Supports. PGA ~ 0.30g



Excessive differential movements leads to failures
Switch steel structures and bus supports
use I-beams, low frequencies,
twisting / torsion. All this is readily computed.
Suitable connectors are available.
Do utilities (and their A/Es) turn a blind eye?
Sunshine will expose the weaknesses.
CEA, ML&P and MEA all have work to do.

ML&P

- 3 115 kV substations tripped immediately (oil level and PT issues). Sub 6 115 kV bus damage.
- Plant 1 35 kV bus
- Plant 2A Units 10 and 11 tripped. SPP tripped.
- Eklutna PT and CT rooftop failures (3 total). PGA 0.17g
- Significant distribution damage.
- 30,800 customers. Power to 8,500 customers by 1 pm. 10,000 customers by 11 pm. All customers by 5 am Dec 1. About 10 Million CM.
- Mostly restored by Dec 1 3 am.
- \$1.3 million repair cost.

ML&P Eklutna



3 of 6 PT / CT damaged. Transformers slid (a bit). Minor damage to buildings

ML&P Damage



Rigid bus



Underground TR

CEA

- 69,000 customers. 4,291 customers out at 1:53 pm. About 2 Million CM (might be low).
- Major damage at Point Mackenzie 230 kV (\$2 to \$7 million)
- Tilted transformers and switchgear (Latouche) \$2 million.
- East Cable 230 kV terminal; Beluga power plant distribution transformer, Teeland switches, Airport foundations cracked, Pt Woronzol leaking bushings, Boniface substation, Dowling substation, University substation (settlement and broken switches), Hillside substation, Huffman substation. \$0.5 million.
- Eklutna tunnel, others. \$1.5 million.
- \$7 million (to \$12 million) repair cost.

CEA
Pt MacKenzie 2018
230 138 kV
Lat 61.2496
Long -150.0268

"Major Damage" of
230 kV Yard




Image © 2019 DigitalGlobe

94 m

1996


Imagery Date: 7/30/2018 lat 61.249570° lon -150.026851° elev 31 m


Google



North


230 kV Yard

 Damaged

 Undamaged

CEA
Pt MacKenzie 2018
230 138 kV
Lat 61.2496
Long -150.0268

North




230 kV Yard

Yard Status December 4 2018







 Damaged




Double End Break 230 kV Switch




The switches are a hybrid between original Siemens Allis, with replaced parts by Southern States



Undamaged





 Damaged









 Damaged





Damaged






Damaged




Rocking lack of stiffeners
Low frequency




 Damaged




Flex Bus did not have enough slack

 Damaged




 Damaged




 Damaged



 Damaged



 Damaged

±4 inches (A)




Plunger Device


Bus pushes on the Switch.
Switch pushes on the Bus.
Leads to high M at bottom of switch
($P_x + P_y + P_z$) * L exceeds moment capacity of porcelain.
 P_x (axial) alone is not the sole culprit.
The rigid bus "plunger" hardware, if not designed properly is not acceptable.

±2 inches (B)

±4 inches (C)



Transverse relative movements
Between the switch and bus
May have been the primary reason
for the porcelain post failures


 Damaged







SHOULD THE STEEL STAND BE RETAINED?
\$7 MILLION DOLLAR QUESTION

Photo after disassembly


 Damaged






Damaged




 Damaged





No damage





SHOULD THE STEEL STAND BE RETAINED?
\$7 MILLION DOLLAR QUESTION

Damage Summary

Description	Phases Damaged
Low level switch	A \emptyset
Low level switch	None
Low level switch	C \emptyset
Low level switch	A \emptyset , C \emptyset
Low level switch	C \emptyset
Low level switch	None
High level switch	B \emptyset
Broken connection	B \emptyset
Low level switch	None
Low level switch	A \emptyset
Low level switch	A \emptyset , C \emptyset
Low level switch	A \emptyset , C \emptyset
Low level switch	C \emptyset
Low level switch	A \emptyset
High level switch	B \emptyset
Broken connection	B \emptyset
Low level switch	A \emptyset , C \emptyset
Low level switch	None
Low level switch	A \emptyset , C \emptyset
Low level switch	None
Low level switch	None
Low level switch	A \emptyset
High level switch (unique)	None
High level switch	None

Low Switches - Dynamics

EW 4.1 HZ
NS 2.4 HZ

Mode	Frequency (Hz)	Primary Modal Directions
1	2.4	NS
2	2.9	NS
3	4.1	EW, Vertical
4	4.8	NS
5	5.2	Vertical, EW
6	8.2	EW, Vertical
7	8.3	NS
8	8.5	NS
9	10.3	NS
10	10.9	NS
11	11.4	Vertical, EW
12	11.5	NS
13	12.2	EW, Vertical
14	12.5	NS
15	13.0	EW, Vertical
16	15.3	Vertical
17	19.4	EW, Vertical
18	19.5	Vertical, EW
19	19.6	EW, Vertical
20	29.8	NS

Table 5-5. "Switch Low" Frequencies

Location	NS (Inches)	EW (Inches)	Vertical (Inches)
Phase A Base	1.47	0.32	0.44
Phase B Base	1.03	0.32	0.05
Phase C Base	1.47	0.32	0.44
Phase A Top	3.78	1.41	1.63
Phase B Top	3.12	0.41	1.43
Phase C Top	3.78	1.42	1.63

Table 5-6. "Switch Low" Displacement Responses

High Switches - Dynamics

Mode	Frequency (Hz)	Primary Modal Directions
1	1.0	EW of the A Frame
2	2.5	NS, Vert
3	4.0	Vert, NS
4	4.1	EW
5	4.6	Vert, EW, NS
6	5.3	Vert, NS, EW
7	5.3	Vert, NS, EW
8	6.0	NS, Vert
9	6.9	NS, Vert
10	7.2	NS, Vert
11	7.4	Vert
12	8.3	Vert
13	9.2	Vert
14	9.6	Vert, NS
15	9.9	Vert, NS
16	10.3	Vert, NS
17	10.4	Vert, EW, NS
18	10.5	Vert
19	10.9	Vert, NS, EW
20	11.2	NS, Vert
21	11.4	NS, Vert
22	14.2	EW
23	19.1	NS
24	19.5	Vert
25	19.6	Vert
26	19.6	Vert, NS
27	19.8	NS
28	20.3	EW
29	23.3	NS
30	23.9	NS, Vert
31	24.4	NS
32	25.3	NS, Vert
33	27.3	EW
34	28.0	Vert, NS
35	32.0	NS
36	39.4	Vert

EW 1.0 HZ
NS 2.5 HZ

Location	NS (Inches)	EW (Inches)	Vertical (Inches)
Phase A Base	1.87	10.22	0.68
Phase B Base	3.60	10.22	0.80
Phase C Base	1.97	10.22	0.68
Phase A Top	1.95	10.67	0.92
Phase B Top	3.92	9.95	1.32
Phase C Top	2.02	10.67	0.92

Observations (I)

- Yard Re-build using new 4-leg supports and new IEEE 693 Switches: **\$7 Million**
- Yard Re-build using original 2-leg supports and new Switches: **\$2 Million**
- CEA, Switch Vendors and Local AK A/E: original leaning towards \$7 million. After external review, adopting \$2 million.
- This weakness is prevalent throughout the Anchorage area. An area-wide assessment with mitigation is RIPE.
- FEMA can pay. CEA, ML&P and MEA should step up to the plate.

Observations (2)

- IEEE 693 is a Guideline. Not Mandatory.
- BC, WA, OR, CA. Mitigation of the bus remains important. The West Coast is not "done".
- IEEE 693 / 1527 / SERA. Field observations and displacement calculations will uncover nearly all of these weaknesses at Anchorage substations. Fixing this is "straightforward". More than half of residual weaknesses at modern substations remain with flex bus and rigid bus adverse interactions.

More Information

- TCLEE No. 5A Report: Overview of all lifeline performance in the Anchorage 2018 earthquake
- <http://www.geEngineeringSystems.com>
- Free
- Detailed report. Point MacKenzie Substation. G&E Report dated July 30 2018 (104 pages). Upon request (NDA)